Timestamp	Observation:	Room Number or Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	FACILITIES WORK ORDER NUMBER	IEQ WORK ORDER NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
3/6/2018 12:39:	01A. ODOR: Unusual or offensive	319		Х							
3/6/2018 12:53:	01B. TEMPERATURE:	304				64611					
	01B. TEMPERATURE:										
3/6/2018 13:24:	03. FOOD: Unsealed.	335				64611					
3/6/2018 12:23:	left in room, dirty lunch boxes	Coat closet - left of theater		х							
3/6/2018 12:20:	04: VENTS: Dirty, obstructed (Wall, (Ceiling)	218			x						
3/6/2018 12:27:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Coat closet - right of theater			x						
3/6/2018 12:32:	04: VENTS: Dirty, obstructed (Wall,	Girls bathroom across from 224			X						
3/6/2018 12:33:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Boys bathroom across from 226			x						
3/6/2018 12:39:	04: VENTS: Dirty, obstructed (Wall, (Ceiling)	238			x						
3/6/2018 12:50:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	151 storage closet			x						
3/6/2018 13:01:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Room 125 bathroom			x						
3/6/2018 13:06::	04: VENTS: Dirty, obstructed (Wall,	Boys bathroom next to 211			x						
3/6/2018 13:08:	04: VENTS: Dirty, obstructed (Wall, (Ceiling)	C-211			x						
3/6/2018 13:08:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Women's bathroom even side 3rd floor	Dust on inside of vents		x						
3/6/2018 13:09:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Girls room near 211			x						
3/6/2018 13:09:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	School store storage closet	There is also a damage tile in this room		x						
3/6/2018 13:14:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	332	Dust inside vent		x						
3/6/2018 13:18:	04: VENTS: Dirty, obstructed (Wall, Ceiling)	Server room in media a center			x						
3/6/2018 13:32:	04: VENTS: Dirty, obstructed (Wall,	C323			x						

T:	Oh ti	Room Number or	0		011070711	FACILITIES WORK ORDER	IEQ WORK ORDER	100101177		20.5.14	0.00==
Timestamp	Observation:	Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
	04: VENTS: Dirty,	01-#									
3/6/2018 13:33:	obstructed (Wall,	Staff women's room odd side	Inside vent		x						
3/0/2010 13.33.	05: TEMPERATURE	Side	mode vent		^						
3/6/2018 12:32	SENSORS: Blocked	311	Drywall repair			64615					
0/0/2010 12:02:	05: TEMPERATURE	011	Drywan ropan			0.010					
3/6/2018 13:06:	: SENSORS: Blocked	322				64615					
	06: CLEANLINESS:		Clutter around teachers								
3/6/2018 12:19:		319	desk	X							
	06: CLEANLINESS:										
3/6/2018 12:44:	: Dust, trash	300		X							
	06: CLEANLINESS:		Lots of piles of								
3/6/2018 12:47:	: Dust, trash	308	papers/clutter piled up	X							
	06: CLEANLINESS:		Papers, boxes books								
3/6/2018 12:49:	Dust, trash	310	piled up around room	X							
	06: CLEANLINESS:										
3/6/2018 12:56:		302	Piled up boxes paper etc	X							
	06: CLEANLINESS:										
3/6/2018 13:02:	 '	318		X							
0/0/0040 40:00:	06: CLEANLINESS:	3rd floor hallway outside	Tape on Ceiling outside								
3/6/2018 13:06:		room 322	room 322		X						
2/6/2019 12:10:	06: CLEANLINESS:	328		x							
3/6/2018 13:10:	<u> </u>	320		^							
3/6/2018 13:12:	06: CLEANLINESS:	C330	Carts and trashcans		x						
3/0/2010 13.12.	08: CEILING TILES:	C330	Carts and trasnicans		^						
	Stained, broken, holes,										
3/6/2018 12:15:		214			x						
	08: CEILING TILES:										
	Stained, broken, holes,										
3/6/2018 12:22:	: painted	212			X						
	08: CEILING TILES:										
0/0/0040 40:00:	Stained, broken, holes,	0.47	Chain on vent /Fix holes		V						
3/6/2018 12:23:	,	317	in drywall		Х						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 12:26:		315	Numerous		x						
	08: CEILING TILES:										
	Stained, broken, holes,	Stairwell to theater									
3/6/2018 12:26:	: painted	balcony	Broken tile		X						
	08: CEILING TILES:										
0/0/0040 40 55	Stained, broken, holes,	000									
3/6/2018 12:28:	+'	226			Х						
	08: CEILING TILES:	Ctoinvoll cutoide of									
3/6/2018 12:32:	Stained, broken, holes,	Stairwell outside of 135/137			x						
5.0,2010 12.02.	08: CEILING TILES:	100/10/			,,						
	Stained, broken, holes,										
3/6/2018 12:33:		311			Х						
	08: CEILING TILES:										
	Stained, broken, holes,										
3/6/2018 12:35:	: painted	232			X						
	08: CEILING TILES:										
2/6/2012 12:07	Stained, broken, holes,	200			_						
3/6/2018 12:37:	painted	309		I	Х		I			L	

		Poom Number or				FACILITIES WORK ORDER	IEQ WORK ORDER				
Timestamp	Observation:	Room Number or Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
	08: CEILING TILES:										
3/6/2018 12:38:	Stained, broken, holes,	238			x						
3/0/2016 12.36.	08: CEILING TILES:	230			^						
	Stained, broken, holes,										
3/6/2018 12:40:		301			X						
	08: CEILING TILES:	Ititi									
3/6/2018 12:42:	Stained, broken, holes,	Location above media center	Dust on vents/		X						
	08: CEILING TILES:										
0/0/0040 40 40	Stained, broken, holes,	S167a and chorus									
3/6/2018 12:43:	+'	practice room 2	Numerous tiles		Х						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 12:43:		300			X						
	08: CEILING TILES:										
3/6/2018 12:48:	Stained, broken, holes,	Art hallway			x						
0,0,201012110	08: CEILING TILES:	7 at riamitaly									
	Stained, broken, holes,										
3/6/2018 12:52:		304			Х						
	08: CEILING TILES: Stained, broken, holes,	Women's room next to									
3/6/2018 12:52:		223			X						
	08: CEILING TILES:										
3/6/2018 12:52:	Stained, broken, holes,	S155			x						
0/0/2010 12:02:	08: CEILING TILES:	0100			X						
	Stained, broken, holes,	Guidance office former									
3/6/2018 12:55:	•	registar	Light fixture loose		X						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:02:		318			X						
	08: CEILING TILES:										
3/6/2018 13:02:	Stained, broken, holes,	139 Storage	Stained tiles		x						
3/0/2010 13:02.	08: CEILING TILES:	109 Storage	Two tiles behind block		^						
	Stained, broken, holes,		column near Windows								
3/6/2018 13:02:	'	Faculty planned ng	need to be replaced		X						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:04:		312			x						
	08: CEILING TILES:										
3/6/2018 13:05:	Stained, broken, holes,	211	Located above side chalkboard		x						
3/3/2010 13.05.	08: CEILING TILES:	211	CHAINDUALU		^						
	Stained, broken, holes,	Hallway to media center									
3/6/2018 13:10:	1	outside C-211			Х					ļ	
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:10:		326			X						
	08: CEILING TILES:										
3/6/2018 13:11:	Stained, broken, holes,	Media center nearTV			x						
3/0/2018 13:11:	08: CEILING TILES:	studio			<u> ^</u>			 		 	
	Stained, broken, holes,										
3/6/2018 13:11:		330			Х						

		Doom Number or				FACILITIES WORK ORDER	IEQ WORK ORDER				
Timestamp	Observation:	Room Number or Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
	08: CEILING TILES:					-	-				
	Stained, broken, holes,				.,						
3/6/2018 13:11	· · · · · · · · · · · · · · · · · · ·	328			Х						\vdash
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:13		336			X						
	08: CEILING TILES:										
	Stained, broken, holes,										
3/6/2018 13:14	+ '	In dark room in 206			Х						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:15		332			X						
	08: CEILING TILES:										
	Stained, broken, holes,										
3/6/2018 13:15	<u>'</u>	338			Х						\vdash
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:15		Kitchen locker room			X						
	08: CEILING TILES:										
	Stained, broken, holes,				.,						
3/6/2018 13:17	+'	334			Х						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:18		333			Х						
	08: CEILING TILES:										
0/0/0040 40 40	Stained, broken, holes,	Server room in media			.,						
3/6/2018 13:19	<u>'</u>	center	Above AC unit		Х						
	08: CEILING TILES: Stained, broken, holes,										
3/6/2018 13:25		335			Х						
	08: CEILING TILES:										
0/0/0040 40:05	Stained, broken, holes,	Ond flace Main landing			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						
3/6/2018 13:25		3rd floor Main landing			X						
	08: CEILING TILES: Stained, broken, holes,		And broken tile above								
3/6/2018 13:27		11	laundry		Х						
	08: CEILING TILES:										
3/6/2018 13:27	Stained, broken, holes,	325			x						
3/0/2010 13.27	08: CEILING TILES:	323			^					+	\vdash
	Stained, broken, holes,										
3/6/2018 13:27	: painted	331			Х						
	08: CEILING TILES:										
3/6/2018 13:29	Stained, broken, holes,	327			x						1
3/3/2010 13.29	08: CEILING TILES:	321			^						\vdash
	Stained, broken, holes,										1
3/6/2018 13:30	: painted	321			Х						
	08: CEILING TILES:										
3/6/2018 13:33	Stained, broken, holes,	323			x						
5/5/2010 15.55	08: CEILING TILES:	323			^						\vdash
	Stained, broken, holes,										
3/6/2018 13:34	: painted	Boys locker room office	Damaged tile		Х						

		Room Number or				FACILITIES WORK ORDER	IEQ WORK ORDER				
Timestamp	Observation:	Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
	09. WATER DAMAGE: Spotting, mildew, paint irregularities (ceilings, walls, doors, windows)	305	holes in block/dust on ceiling tiles		X	No.	NO. INC.			JO DAN NETON	020020
	09. WATER DAMAGE: Spotting, mildew, paint irregularities (ceilings, walls, doors, windows)	C112	Stained drywall. Still wet. Will need to remove impacted drywall. Replace with green board			64617					
3/6/2018 12:39:	11. NON-ISSUED HCPSS FURNITURE AND APPLIANCES	165	Microwave	×							
	11. NON-ISSUED HCPSS FURNITURE AND APPLIANCES	304		X							
3/6/2018 12:57:	11. NON-ISSUED HCPSS FURNITURE AND APPLIANCES	306		x							
3/6/2018 12:58:	11. NON-ISSUED HCPSS FURNITURE : AND APPLIANCES	310		Х							
3/6/2018 13:16:	11. NON-ISSUED HCPSS FURNITURE AND APPLIANCES	338		X							
3/6/2018 13:32:	11. NON-ISSUED HCPSS FURNITURE AND APPLIANCES	Staff women's room odd side		X							
3/6/2018 12:31:	12. FABRIC MATERIALS: Stuffed animals, beanbags, pillows, blankets, rugs,	A135	Bean bag chairs	x							
<u> </u>	12. FABRIC MATERIALS: Stuffed animals, beanbags, pillows, blankets, rugs,	71100	Source Sag Chaire								
3/6/2018 12:45:		S167c	Snowman	X							
	MATERIALS: Stuffed animals, beanbags, pillows, blankets, rugs,										
3/6/2018 12:54:	12. FABRIC MATERIALS: Stuffed animals, beanbags, pillows, blankets, rugs,	Guidance - conf room 2		X							
3/6/2018 13:03:	12. FABRIC MATERIALS: Stuffed animals, beanbags, pillows, blankets, rugs,	141	Blankets on wall	X							
3/6/2018 13:18:	12. FABRIC MATERIALS: Stuffed	Custodial office	Stuffed animals	X							
3/6/2018 13:30:	animals, beanbags, pillows, blankets, rugs, tetc.	Office in girls locker room		x							

		Room Number or				FACILITIES WORK ORDER	IEQ WORK ORDER				
Timestamp	Observation:	Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
3/6/2018 12:57:	14. MATERIALS/CHEMICA LS: Improperly stored or marked	Guidance - conference room 1	Items hanging from ceiling	x							
3/6/2019 13:14:	15. FLOORS: Coverings not level or secure (tile, carpets, wood board, etc.)	336		x							
3/0/2018 13.14.	15. FLOORS: Coverings not level or secure (tile, carpets,	330		^							
3/6/2018 13:21:	wood board, etc.)	337		Х							
3/6/2018 12:33:	18. PLANTS: NO ARTIFICIAL. LIVE - Waterproof barriers in place	S133	Fake plants.	x							
3/6/2018 12:58:	18. PLANTS: NO ARTIFICIAL. LIVE - Waterproof barriers in place	Guidance main conference room		x							
3/6/2018 13:13:	18. PLANTS: NO ARTIFICIAL. LIVE - Waterproof barriers in	160	On wall	x							
	18. PLANTS: NO ARTIFICIAL. LIVE - Waterproof barriers in										
3/6/2018 13:15: 3/6/2018 12:28:	19. SINKS AND FOUNTAINS: Drain slowly, work improperly,	Kitchen office Girls br odd side	Wreath Girls bathroom outside 317	X		64619					
3/6/2018 12:53:	19. SINKS AND FOUNTAINS: Drain slowly, work improperly, leak	223				64619					
3/6/2018 12:36:	23. ELECTRICAL: Electrical outlets not secured, cover missing, frayed wires on	303				64620					
3/6/2018 12:48:	23. ELECTRICAL: Electrical outlets not secured, cover missing, frayed wires on	310				64620					
3/6/2018 13:07:	23. ELECTRICAL: Electrical outlets not secured, cover missing, frayed wires on equipment	138	Missing escutian plate			64620					
3/6/2018 13:31:	23. ELECTRICAL: Electrical outlets not secured, cover missing, frayed wires on equipment	321				64620					

		Room Number or				FACILITIES WORK ORDER	IEQ WORK ORDER				
Timestamp	Observation:	Location/Name:	Comments for this room:	ADMINISTRATION	CUSTODIAL	NUMBER	NUMBER	ASSIGNED DATE	COMPLETION DATE	30-DAY REVISIT	CLOSED
3/6/2018 12:25:	38. EXTERIOR LIGHTS: Not working, broken, missing	220	Light covers need to be replaced or repaired			64620					
3/6/2018 12:34:	42. PAVEMENT: Damaged, failing,	S133	Stair step crack in CMU			64625					
3/6/2018 12:21:	·	C319	Remove ladder and furniture		X	0.1920					
3/6/2018 12:30:		Stairwell 1 3rd floor	Fix ceiling tiles		x						
3/6/2018 12:39:	:	307	Chain hanging	х							
3/6/2018 12:42:	:	233	I light cover in ceiling needs replacing			64627					
3/6/2018 12:42:	:	Wall outside 300	Hole in block			64628					
3/6/2018 12:43:	:	237	Replace 1 light cover			64627					
3/6/2018 12:45:	:		Water stain on light cover near windows		х						
3/6/2018 12:49:	:		Only 1 sprinkler head. Should there be more?	х							
3/6/2018 12:53:	:	Ladies room next to 223	Replace ring around sprinkler head		x						
3/6/2018 12:59:	:	Vent outside 316	Vent cover			64629					
3/6/2018 13:01:		Teacher planning	Light cover near book shelves needs to be replaced			64627					
3/6/2018 13:04:		Woman's bathroom staff even side	Hanging ceiling tile		x						
3/6/2018 13:04:			Light cover needs to be adjusted. Doesn't seat properly			64627					
3/6/2018 13:06:	:	322	Lights flicker			64627					
3/6/2018 13:09:	:	Men's even side third floor	Hole in cinder blocks			64628					
3/6/2018 13:09:		324	Light panel not very secure			64627					
3/6/2018 13:22:		339	Eye wash station sprays onto floor excessively			64630					
3/6/2018 13:29:			Sprinkler missing rim plate			64631					